

H. Supporting Information for Exceedance Investigation and Findings

Photo 1 Provision of wastewater treatment facilities and proper drainage system as mitigation measure



Photo 2 Wastewater treatment facilities (AquaSed, sedimentation tanks) inside the site (near discharge outlet to the northern ditches)



Photo 3 Appearance of the water body at MP3 on 1 September 2025



Photo 4 Appearance of the water body at MP3 on 3 September 2025



Photo 5 Appearance of the water body at MP3 on 5 September 2025



Photo 6 Appearance of the water body at MP3 on 8 September 2025



Photo 7 **Appearance of the water body at MP3 on 10 September 2025**



Photo 8 **Appearance of the water body at MP3 on 12 September 2025**



Photo 9 **Appearance of the water body at MP3 on 15 September 2025**



Photo 10 **Appearance of the water body at MP3 on 17 September 2025**



Photo 11 Appearance of the water body at MP3 on 19 September 2025



Photo 12 Appearance of the water body at MP3 on 22 September 2025



Photo 13 **Appearance of the water body at MP3 on 26 September 2025**



Photo 14 **Appearance of the water body at MP3 on 29 September 2025**



Photo 15 **Appearance of the water body at MP4 on 3 September 2025**



Photo 16 **Appearance of the water body at MP4 on 5 September 2025**



Photo 17 **Appearance of the water body at MP5 on 3 September 2025**



Photo 18 **Appearance of the water body at MP5 on 5 September 2025**



Photo 19 **Appearance of the water body at MP5 on 10 September 2025**



Photo 20 **Appearance of the water body at MP5 on 12 September 2025**



Photo 21 **Appearance of the water body at MP5 on 15 September 2025**



Photo 22 **Appearance of the water body at MP5 on 22 September 2025**



Photo 23 **Appearance of the water body at MP6 on 5 September 2025**



Photo 24 **Appearance of the water body at MP6 on 12 September 2025**



Photo 25 **Appearance of the water body at MP6 on 15 September 2025**



Photo 26 **Appearance of the water body at MP6 on 22 September 2025**

