

H. Supporting Information for Exceedance Investigation and Findings

Photo 1 Provision of wastewater treatment facilities and proper drainage system as mitigation measure



Photo 2 Wastewater treatment facilities (AquaSed, sedimentation tanks) inside the site (near discharge outlet to the northern ditches)



Photo 3

Appearance of the water body at MP3 on 1 November 2025



Photo 4

Appearance of the water body at MP3 on 3 November 2025



Photo 5 Appearance of the water body at MP3 on 5 November 2025



Photo 6 Appearance of the water body at MP3 on 7 November 2025



Photo 7 Appearance of the water body at MP3 on 10 November 2025



Photo 8 Appearance of the water body at MP3 on 12 November 2025



Photo 9 Appearance of the water body at MP3 on 14 November 2025



Photo 10 Appearance of the water body at MP3 on 17 November 2025



Photo 11 **Appearance of the water body at MP3 on 19 November 2025**



Photo 12 **Appearance of the water body at MP3 on 21 November 2025**



Photo 13 Appearance of the water body at MP3 on 24 November 2025



Photo 14 Appearance of the water body at MP3 on 26 November 2025



Photo 15 Appearance of the water body at MP3 on 28 November 2025



Photo 16 Appearance of the water body at MP4 on 5 November 2025



Photo 17 **Appearance of the water body at MP4 on 24 November 2025**



Photo 18 **Appearance of the water body at MP6 on 24 November 2025**

