

H. Supporting Information for Exceedance Investigation and Findings

Photo 1 Provision of wastewater treatment facilities and proper drainage system as mitigation measure



Photo 2 Wastewater treatment facilities (AquaSed, sedimentation tanks) inside the site (near discharge outlet to the northern ditches)



Photo 3

Appearance of the water body at MP3 on 1 December 2025



Photo 4

Appearance of the water body at MP3 on 3 December 2025



Photo 5 Appearance of the water body at MP3 on 5 December 2025



Photo 6 Appearance of the water body at MP3 on 8 December 2025



Photo 7 Appearance of the water body at MP3 on 10 December 2025



Photo 8 Appearance of the water body at MP3 on 12 December 2025



Photo 9 Appearance of the water body at MP3 on 15 December 2025



Photo 10 Appearance of the water body at MP3 on 17 December 2025



Photo 11 Appearance of the water body at MP3 on 19 December 2025



Photo 12 Appearance of the water body at MP3 on 22 December 2025



Photo 13 Appearance of the water body at MP3 on 24 December 2025



Photo 14 Appearance of the water body at MP3 on 27 December 2025



Photo 15 Appearance of the water body at MP3 on 29 December 2025



Photo 16 Appearance of the water body at MP3 on 31 December 2025



Photo 17 **Appearance of the water body at MP4 on 15 December 2025**



Photo 18 **Appearance of the water body at MP5 on 1 December 2025**

