

H. Supporting Information for Exceedance Investigation and Findings

Photo 1 Provision of wastewater treatment facilities and proper drainage system as mitigation measure



Photo 2 Wastewater treatment facilities (AquaSed, sedimentation tanks) inside the site (near discharge outlet to the northern ditches)



Photo 3 Appearance of the water body at MP3 on 2 January 2026



Photo 4 Appearance of the water body at MP3 on 5 January 2026



Photo 5 Appearance of the water body at MP3 on 7 January 2026



Photo 6 Appearance of the water body at MP3 on 9 January 2026



Photo 7 Appearance of the water body at MP3 on 12 January 2026



Photo 8 Appearance of the water body at MP3 on 14 January 2026



Photo 9 **Appearance of the water body at MP3 on 16 January 2026**



Photo 10 **Appearance of the water body at MP3 on 19 January 2026**



Photo 11 Appearance of the water body at MP3 on 21 January 2026



Photo 12 Appearance of the water body at MP3 on 23 January 2026



Photo 13 Appearance of the water body at MP3 on 26 January 2026



Photo 14 Appearance of the water body at MP3 on 28 January 2026



Photo 15 **Appearance of the water body at MP3 on 30 January 2026**



Photo 16 **Appearance of the water body at MP5 on 19 January 2026**



Photo 17

Appearance of the water body at MP6 on 19 January 2026



Photo 18

Appearance of the water body at MP6 on 28 January 2026

