



Photo 1: The Construction works have been screened by hoarding (CM2)



Photo 2: The wetland areas are being established, with the ponds are being seasonally filled with rain water. (CM2)



Photo 3: Continuous belt of screen planting along the southern and western boundaries of the site has been completed. (CM6)



Photo 4: Advance screen planting of noise barrier has been undertaken (CM6)