

Appendix M. Landscape and Visual Audit Photos

	
<p>Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)</p>	<p>Photo 2: The wetland areas are being established, with the ponds are being seasonally filled with rain water.(CM2)</p>
 <p>2015 10 26</p>	
<p>Photo 3: Continuous belt of screen planting along the southern and western boundaries of the site has been completed. (CM6) Advance screen planting of noise barrier has been undertaken. (CM6)</p>	