

Appendix M. Landscape and Visual Audit Photos

 <p>A photograph showing a construction site. In the foreground, there is a row of red and white plastic noise barriers. Behind them is a grey hoarding wall. The background shows a line of trees and a hazy sky. A date stamp '2016.03.29' is visible in the bottom right corner of the photo.</p>	 <p>A photograph of a wetland area. There are several ponds of varying sizes, some filled with water and others with mud. The surrounding area is covered with green vegetation. A date stamp '2016.03.29' is visible in the bottom right corner of the photo.</p>
<p>Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)</p>	<p>Photo 2: The wetland areas are being established, with the ponds are being seasonally filled with rain water.(CM2)</p>
 <p>A photograph showing a close-up view of a noise barrier. The barrier is made of green metal posts and panels. In the foreground, there are several young trees and plants, some of which are supported by stakes. A date stamp '2016.03.29' is visible in the bottom left corner of the photo.</p>	
<p>Photo 3: Advance screen planting of noise barrier has been undertaken. (CM6)</p>	