

M. Landscape and Visual Audit Photos

 <p>A photograph showing a construction site. A green noise barrier is visible, partially obscuring a pond in the background. The foreground is a dirt path with some vegetation. A date stamp '2017/08/29' is visible in the bottom right corner.</p>	 <p>A photograph of a wetland area. A pond is filled with water, reflecting the sky and surrounding trees. The area is lush with greenery. A date stamp '2017/08/29' is visible in the bottom right corner.</p>
<p>Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)</p>	<p>Photo 2: The wetland areas are being established, with the ponds are being seasonally filled with rain water. (CM2)</p>
 <p>A photograph showing a dense planting of trees and plants. The plants are lush green and appear to be part of a noise barrier. A date stamp '2017/08/29' is visible in the bottom right corner.</p>	
<p>Photo 3: Advance screen planting of noise barrier has been undertaken (CM6)</p>	