

M. Landscape and Visual Audit Photos



Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)



Photo 2: The wetland areas are being established, and the ponds are being seasonally filled with rain water. (CM2)



Photo 3: Advance screen planting of noise barrier has been undertaken (CM6)