

## M. Landscape and Visual Audit Photos

|                                                                                               |                                                                                                                          |
|-----------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|
|              |                                        |
| <p>Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)</p> | <p>Photo 2: The wetland areas are being established, and the ponds are being seasonally filled with rainwater. (OM4)</p> |
|            |                                                                                                                          |
| <p>Photo 3: Advance screen planting of noise barrier has been undertaken (CM6, OM2)</p>       |                                                                                                                          |