

M. Landscape and Visual Audit Photos

	
Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)	Photo 2: The wetland areas have been established, and the ponds are being seasonally filled with rainwater. (OM4)
	
Photo 3: Advance screen planting of noise barrier has been undertaken (CM6, OM2)	