


M. Landscape and Visual Audit Photos

| | |
|---|--|
|  |  |
| <p>Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)</p> | <p>Photo 2: The wetland areas have been established, and the ponds are being seasonally filled with rainwater. (OM4)</p> |
|  | |
| <p>Photo 3: Advance screen planting of noise barrier has been undertaken (CM6, OM2)</p> | |