

H. Supporting Information for Exceedance Investigation and Findings

Photo 1 Provision of wastewater treatment facilities and proper drainage system as mitigation measure



Photo 2 Wastewater treatment facilities (AquaSed, sedimentation tanks) inside the site (near discharge outlet to the northern ditches)



Photo 3 **Appearance of the water body at MP3 on 3 March 2025**



Photo 4 **Appearance of the water body at MP3 on 5 March 2025**



Photo 5 **Appearance of the water body at MP3 on 24 March 2025**



Photo 6 **Appearance of the water body at MP3 on 28 March 2025**



Photo 7 **Appearance of the water body at MP3 on 31 March 2025**



Photo 8 **Appearance of the water body at MP4 on 3 March 2025**




Photo 9 **Appearance of the water body at MP4 on 14 March 2025**



Photo 10 **Appearance of the water body at MP4 on 17 March 2025**



Photo 11 **Appearance of the water body at MP4 on 24 March 2025**



Photo 12 **Appearance of the water body at MP4 on 26 March 2025**



Photo 13 **Appearance of the water body at MP4 on 28 March 2025**



Photo 14 **Appearance of the water body at MP4 on 31 March 2025**



Photo 15 **Appearance of the water body at MP5 on 3 March 2025**



Photo 16 **Appearance of the water body at MP5 on 24 March 2025**



Photo 17 **Appearance of the water body at MP6 on 3 March 2025**



Photo 18 **Appearance of the water body at MP6 on 5 March 2025**



Photo 19 **Appearance of the water body at MP6 on 24 March 2025**

