




N. Landscape and Visual Audit Photos

 <p>16/5/2025</p>	 <p>16/5/2025</p>
<p>Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)</p>	<p>Photo 2: The wetland areas have been established, and the ponds are being seasonally filled with rainwater. (OM4)</p>
 <p>16/5/2025</p>	
<p>Photo 3: Advance screen planting of noise barrier has been undertaken (CM6, OM2)</p>	