

## H. Supporting Information for Exceedance Investigation and Findings

**Photo 1** Provision of wastewater treatment facilities and proper drainage system as mitigation measure



**Photo 2** Wastewater treatment facilities (AquaSed, sedimentation tanks) inside the site (near discharge outlet to the northern ditches)



**Photo 3**      **Appearance of the water body at MP3 on 2 February 2026**



**Photo 4**      **Appearance of the water body at MP3 on 4 February 2026**



**Photo 5**      **Appearance of the water body at MP3 on 6 February 2026**



**Photo 6**      **Appearance of the water body at MP3 on 9 February 2026**



**Photo 7**      **Appearance of the water body at MP3 on 11 February 2026**



**Photo 8**      **Appearance of the water body at MP3 on 13 February 2026**



**Photo 9**      **Appearance of the water body at MP3 on 25 February 2026**



**Photo 10**      **Appearance of the water body at MP3 on 27 February 2026**

