

# N. Landscape and Visual Audit Photos

|                                                                                                      |                                                                                                                   |
|------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|
|  <p>02/06/2026</p>  |  <p>02/06/2026</p>              |
| Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)               | Photo 2: The wetland areas have been established, and the ponds are being seasonally filled with rainwater. (OM4) |
|  <p>02/06/2026</p> |                                                                                                                   |
| Photo 3: Advance screen planting of noise barrier has been undertaken (CM6, OM2)                     |                                                                                                                   |