

H. Supporting Information for Exceedance Investigation and Findings

Exceedance

Photo 1 Provision of wastewater treatment facilities and proper drainage system as mitigation measure on 21 August 2026



Photo 2 Wastewater treatment facilities (AquaSed, sedimentation tanks) inside the site (near discharge outlet to the northern ditches) on 7 August 2026



Exceedance

Photo 3 Appearance of the water body at MP3 on 3 August 2026



Photo 4 Appearance of the water body at MP3 on 5 August 2026



Exceedance

Photo 5 Appearance of the water body at MP3 on 7 August 2026



Photo 6 Appearance of the water body at MP3 on 10 August 2026



Exceedance

Photo 7 Appearance of the water body at MP3 on 12 August 2026



Photo 8 Appearance of the water body at MP3 on 14 August 2026



Exceedance

Photo 9 **Appearance of the water body at MP3 on 17 August 2026**



Photo 10 **Appearance of the water body at MP3 on 19 August 2026**



Exceedance

Photo 11 Appearance of the water body at MP3 on 21 August 2026



Photo 12 Appearance of the water body at MP3 on 24 August 2026



Exceedance

Photo 13 Appearance of the water body at MP3 on 26 August 2026



Photo 14 Appearance of the water body at MP3 on 28 August 2026



Exceedance

Photo 15 **Appearance of the water body at MP3 on 31 August 2026**



Photo 16 **Appearance of the water body at MP4 on 14 August 2026**



Exceedance

Photo 17 Appearance of the water body at MP5 on 7 August 2026



Photo 18 Appearance of the water body at MP6 on 10 August 2026



Exceedance

Photo 19 **Appearance of the water body at MP6 on 14 August 2026**



Photo 20 **Appearance of the water body at MP6 on 21 August 2026**

